

AUTOHAZE

Diazo Stain and Ghost Image Remover

DESCRIPTION

Autohaze is an 'all in one' very strong haze remover for occasional use on very stubborn stains.

Applications

Autohaze has been formulated for effective removal of hazes and ghost images commonly left after stencil reclaiming. It negates the need for an additional solvent application.

READ ENTIRE TECHNICAL DATA SHEET BEFORE USING THIS PRODUCT

FEATURES & BENEFITS

- A convenient 'one pot' haze remover paste based on a unique caustic and solvent mixture. Allows rapid and effective removal of ink stains and ghost images in less than 10 minutes.
- Ideal for busy print shops or where maximum haze removal performance is needed.

WORKING INSTRUCTIONS

To remove Stains or Ghost Images

1. Clean off all ink residue prior to stencil removal.
2. Remove stencil with a recommended Autotype decoating chemical product.
3. Apply a small amount of Autohaze to both sides of the wet mesh with a brush, thoroughly covering the stained areas in a circular motion.
4. Leave to stand for 6 to 8 minutes. If left to stand for longer periods, Autohaze can damage the fibres of the mesh.
5. Rinse off residue with gently water spray.
6. Remove stain with high pressure stripper.

Due to partial separation, Autohaze may require stirring if left to stand for long periods.



Autohaze may also be used to degrease and chemically abrade new or used aluminum frames prior to mesh stretching.

New Frames

1. Wet the frame.
2. Apply a small amount of Autohaze to the underside of the frame with a brush.
3. Leave to stand 4 to 5 minutes.
4. Thoroughly wash off all Autohaze residue and leave to dry.

Used Frames

1. Remove any remaining mesh.
2. If any adhesive layer or hardened ink remains, this should first of all be softened with Autosolve.
3. Apply sufficient amounts of Autosolve to soak and penetrate hardened residue.
4. Leave to stand for 5 to 10 minutes. Thoroughly wash off residue with water.
5. Then apply a liberal amount of Autohaze over the hardened residue and leave to stand for 20 to 30 minutes.
6. Wash off thoroughly then use a with a high pressure gun.
7. Should any residue still remain, repeat application of Autohaze only.

For more information on how to use MacDermid Autotype products, go to the How to Guide section at macdermid.com/autotype.

SHELF LIFE & STORAGE

Autohaze should be stored between 5 to 25 °C (40 to 77 °F). Do not freeze or heat.

Shelf life at these conditions is two years.

PACKAGING

Autohaze is available in trade packs of 12 x 1 Kg, 2 x 5 Kg and 25 Kg.



SAFETY & WARNING

MacDermid Autotype recommends that the company/operator read and review the Safety Data Sheets for the appropriate health and safety warnings before use.

Safety Data Sheets are available from MacDermid Autotype.

WASTE TREATMENT

Prior to using any recommendations or suggestions by MacDermid Autotype for waste treatment, the user is required to know the appropriate local/state/federal regulations for on-site or off-site treatment which may require permits. If there is any conflict regarding our recommendations, local/state/federal regulations take precedent.

CONTACT INFORMATION

To confirm this is the most recent issue, please contact MacDermid Autotype
 salessupport@macdermidautotype.com

North America MacDermid Autotype Inc. 5210 Phillip Lee Drive Atlanta, GA 30336, USA (404) 696 4565 autotypeusinfo@macdermid.com	Europe MacDermid Autotype Ltd. Grove Road, Wantage, Oxon OX12 7BZ, UK +44 (0) 1235 771111 salessupport@macdermidautotype.com	Asia MacDermid Autotype Pte Ltd. No, 20 Tuas Avenue 6, Singapore, 639307 +65 689 79670 sginfo@autotype.com
---	--	--

Also read carefully warning and safety information on the Safety Data Sheet. This data sheet contains technical information required for safe and economical operation of this product.
 READ IT THOROUGHLY PRIOR TO PRODUCT USE.

DISCLAIMER: All statements, technical information and recommendations contained herein are based on tests we believe to be reliable, but the accuracy or completeness thereof is not guaranteed. No statement or recommendation shall constitute a representation unless set forth in an agreement signed by officers of seller and manufacturer. NO WARRANTY OR MERCHANTABILITY OR WARRANTY OF FITNESS FOR A PARTICULAR PURPOSE IS MADE. The following warranty is made in lieu of such warranties and all other warranties, express, implied, or statutory. Products are warranted to be free from defects in material and workmanship at the time sold. The sole obligation of seller and manufacturer under this warranty shall be to replace any product defective at the time sold. Under no circumstances shall manufacturer or seller be liable for any loss, damage or expense, direct or consequential, arising out of the inability to use the product. Notwithstanding the foregoing, if products are supplied in response to a customer request that specifies operating parameters beyond those stated above, or if products are used under conditions exceeding said parameters, the customer by acceptance or use thereof assumes all risk of product failure and of all direct, indirect and consequential damages that may result from use of the products under conditions, and agrees to exonerate, indemnify and hold harmless MacDermid Incorporated therefrom. No suggestion for product use nor anything contained herein shall be construed as a recommendation to use any product in infringement of any patent rights, and seller and manufacturer assume no responsibility or liability for any such infringement.

® Registered Trademark of MacDermid Performance Solutions. ™ Trademark of MacDermid Performance Solutions.
 © Platform Specialty Products Corporation and its subsidiaries 2016.

